Reproduced at the National Archives

Date:03/20/94
Page:1

JFK ASSASSINATION SYSTEM

IDENTIFICATION FORM

AGENCY INFORMATION

AGENCY : SSCIA
RECORD NUMBER : 157-10011-10108

RECORDS SERIES :
REPORT

AGENCY FILE NUMBER :

DOCUMENT INFORMATION

ORIGINATOR : FBI
FROM :
TO :

TITLE :
ANALYSIS OF FIREARMS, VEHICLE, ETC.

DATE : 11/23/63
PAGES : 26

SUBJECTS :
COPIES OF PHOTOS; REPORT ON FIREARMS, SPECTROGRAPHIC
MICROSCOPIC ANALYSES; FINGERPRINTS

DOCUMENT TYPE : PAPER, TEXTUAL DOCUMENT
CLASSIFICATION : U
RESTRICTIONS : OPEN IN FULL
CURRENT STATUS : O
DATE OF LAST REVIEW : 03/24/94

OPENING CRITERIA :

COMMENTS :
SSCI Box 337, Folder 12 (VI-C-5-D2)

SSCI Box 337, Folder 12

Record Number 157-10011-10108

R1954

V1-C-5-D2

4/5/77

E6

SENATE SELECT COMMITTEE REQUEST
November 21, 1975

November 6, 1975
Item #4

R DELIVERY

RECEIVED FROM
DEC 1 1975
DOJ

REVIEWED BY FBI/JFK TASK FORCE
ON 11/4/93 Dal
☒ RELEASE IN FULL
☐ RELEASE IN PART
☐ TOTAL DENIAL

PC78243

DC — Secret Ser. Gar Lincoln Presid. limousine 1:30 AM 11/27/


chrome strip
1 1/4"
28"
24"
Inside view

dent (Photo taken)

No direction indicated


Red Rose Petals
Blood
Chrysantemum Boquet

Blood, tissue or bone Frag. scattered over interior of car and on hood — on visors (both sides of rt visor)

3 Frag. lead found on rear floorboard, 2 on rug, 1 in seat hinge channel (Jump Seat

No other frag. found in car
No bullet holes found

ROM
1975
DOJ
Reference copy, JFK Collection: HSCA (RG 233)

11/23

1:30 am
Exam car -


#1223 14
chrome strip
1 3/8"
CK Dent (Photo taken)
JHS
No direction indicated -
28"
24"

Inside view windshield


14 1/2
37"
23"
16 1/2"

outside view

sun visors

Front


Blood,
Chunks
1 ½ one part

Blood, tissue or Bone frag. scattered over interior of car & on hood - on visors (both sides of Rt visor

3 Frags Lead found on Rear Floorboard. 2 on Rug, 1 in seat's hinge channel (Jumps seat.

No other Frags. found in car,

No bullet holes found Rugs not torn out

7C

M

DEC 1963

DOJ

PC78243

DC — Secret Ser. Gar Lincoln Presid. Limousine 1:30 AM 11/23/


chrome strip
dent (Photo taken)
1 1/4"
28"
24"
Inside view

No direction indicated


Red Rose Petals
Blood
Chrysantemum Boquet

Blood, tissue or bone Frag. scattered over interior of car and on hood — on visors (both sides of rt visor)

3 Frag. lead found on rear floorboard, 2 on rug, 1 in seat hinge channel (Jump Seat

No other frag. found in car
No bullet holes found

FROM
This document is [illegible] not for [illegible] 1915
DOJ

Reproduced at the National Archives

RC28247

Lincoln limousine 11/23/63



1 Smear resembling lead on inside

2 Cracks on outside - stellate (radiating)

3 Minute frag missing from outside

Struck by projectile on inside surfac

This document is prepared in response to your request and is not for dissemination outside your Committee. Its use is limited to official proceedings by your Committee and the content may not be disclosed to unauthorized personnel without the express approval of the FBI.

RECEIVED FROM
DEC 1 1975
DOJ

Killion
Frazier
Cunningham
243

8

D 436461AX

11/22/63
11/23/63

Q1



Q1
Bullet from stretcher

C-1

Wt - 158.6 grains

Type MCC (Non-magnetic) 6.5 mm Mannlicher-Carcano (Italian) Solid Pt

L & G - 4 Rt

Land - .07

Groove - .13



07
13
20
x4
80 vs .796 Chart 4R

Mfg: ≈ to W.C.C. __ gr

.257
.314
.826

2
Bullet fragment from seat ~~near~~ driver

2

Wt 44.6 grains - No cannelure

Type Nose portion of MC-C with lead - Full metal jacket type

Land 07
Gr 13
± 6.5 mm + 7 Rt
x4 = 80 = 6.5



44.6
21.0
65.6 gr

3
Bullet from beside ~~front~~ seat

3

Wt = 21.0 gr.

Q2 & Q3 Could be from one or two bullets.

Type = MC Jacket - base only no lead - full metal jacket type

L & G - 4 Rt



Land .07

Groove 13 x4 = 80 vs .796 on chart for 6.5 mm

RECEIVED FRO
DEC 1 1975
DOJ

Lead frag. from head - 1.65 grains 11/23 Bethesda. No Val.
" " " " .15 gr " " " "

Spectro Exam of Same - See GH W.S. Report & Q2 - Q3 & Q1.

(#1 from flooring left side jumpseat 0.9 gr
#2 " " " " " 0.7
(#3 " " " " " 0.7
Q14 No Value

Q9 Lead frag .5 grs - Gov. arm. Q9 No Value

7

14